

CERTIFICATE OF ACCREDITATION



Chemsafety Ltd

Client Number 9360

PO Box 8141, Riccarton, Christchurch, 8440
2B, 303 Blenheim Road, Upper Riccarton, Christchurch, 8041

Telephone 03 366-3700

www.chemsafety.co.nz

Authorised Representative

Mrs Livia Fioravanti
Laboratory Manager

Programme

Chemical Testing Laboratory

Accreditation Number 1328

Initial Accreditation Date 17 June 2019

Conformance Standard

ISO/IEC 17025:2017

General requirements for the competence of testing and calibration laboratories

Laboratory Services Summary

2.64 Asbestos

Operations Manager Authorisation:		Issue 14	Date:10/03/26	Page 1 of 2
--------------------------------------	--	----------	---------------	-------------



Chemsafety Ltd
 Chemical Testing Laboratory
SCOPE OF ACCREDITATION

Accreditation Number 1328

Sampling activities of the laboratory may be carried out elsewhere. Testing for asbestos identification and fibre counts are carried out at the laboratory's premises in Christchurch or at a field site.

2.64 Asbestos

(a) Identification

Sampling and Analysis

Bulk identification using polarised light microscopy

AS 5370:2024 Sampling and Qualitative Identification of Asbestos in Bulk Materials (excluding soils)

(b) Fibre Counts

Sampling and Analysis

Determination of airborne asbestos fibre counts on membrane filters


NOHSC:3003: National Occupational Health and Safety Commission Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos 2nd Edition [NOHSC:3003 (2005)]

(c) Field Sites

Establishment and operation of field sites for the purposes of asbestos fibre counting, in accordance with procedures listed in 2.64(b)

(d) Field Testing

Performance of field testing for the purposes of asbestos fibre counting, in accordance with procedures listed in 2.64(b)

Operations Manager Authorisation:		Issue 14	Date:10/03/26	Page 2 of 2
--------------------------------------	---	----------	---------------	-------------